


Legend


- ⊕ Proposed Turbine Location
- ⬜ Ten x Rotor Diameter from Turbines
- Study Area
- Receptors Within Study Area Not Predicted to Experience Shadow Flicker Effects
- Receptors Predicted to Experience Shadow Flicker Effects <30 Hours per Year
- Receptors Predicted to Experience Shadow Flicker Effects >30 Hours per Year
- Receptors Predicted to Experience Maximum Shadow Flicker Effects >30 Minutes per Day



Produced By: MT	Ref: 3959-REP-098
Checked By: SC	Date: 04/01/2023

Figure 17.1
Shadow Flicker Assessment

Torrance Wind Farm Extension II



Contains OS data © Crown Copyright and database right 2022